Oil Field Environmental Incident Summary

Responsible Party: dynamic support services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name:

Field Name: TIOGA

Date Incident: 1/24/2014

Time Incident: 07:15

Facility ID Number:

Twp: 160

Rng: 94

Sec: 22

Qtr:

Location Description: Spilled on county road 86th street nw for 1/4 mile to 99th ave south for 3 miles

to cty road 16a for 1/2 half mile

Submitted By: thomas snyder Received By:

Contact Person: Kenneth Bird

5401 hwy 8

stanley, nd 58784

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Unknown Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	
Oil	0	barrels	0	barrels	
Brine	13	barrels	13	barrels	
Other	0	barrels	0	barrels	

Description of Other Released Contaminant:

none

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Followup

Units

Potential Environmental Impacts:

none

Action Taken or Planned:

all brine water impregnated soil/road surface was scraped off and hauled away to a approved solid waste disposal site

Wastes Disposal Location: indian hills solid waste disposal

Agencies Involved:

Updates

Date: 1/28/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, Dynamic Support Services truck lost product on county and twp roads for a distance of 3.75 miles. Report states that the impacted roads were bladed and contaminated material picked up for disposal. Volume lost estimated at 13 barrels of brine beginning (?) at 160-94-22 in Burke County. Please follow up and confirm the cleanup through grader and disposal tickets, as well as photos and GPS coordinates.

Date: 1/29/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 1/29/14.

No visible sign of spill at the described location other than areas that look as though new gravel has been brought in.

No followup is necessary.